

# FT 1000

## Trades and Tasks

-Temperature of liquid and soft materials



- Handy thermometer with immersion temperature probe. Pocket size, light weight and easy to use.

### TECHNICAL DATA

Accuracy	+/-3%
Temperature range	-20 - 1000°C (-4 - 1832°F)
Measuring units	°C, °F
HOLD	yes
Low batt indication	yes
Dimensions	117 x 65 x 24 mm
Weight	0,16 kg

### SUPPLIED WITH

Battery, fixed all-purpose probe